

Amprobe Tachometers

- Measures rotational and surface speed
- Contact and non-contact measurement
- Select rpm using infrared beam or adapter: m/min, m/sec, ft/min, ft/sec, in/min, m, ft, in
- Stores maximum, minimum, average & last measurement
- Auto power off function

Includes 6 adapters, carrying case, reflective tapes, 2 AA batteries and user manual

TACH20


SPECIFICATIONS

Measuring Ranges:			
Optical	1 - 99999 RPM		
Mechanical	1 - 19999 RPM		
Speed	Ø 01 m	Ø 6"	Ø 12"
m/min	0.10 - 1999	0.10 - 1524	0.40 - 609.6
ft/min	0.40 - 6550	0.40 - 5000	0.40 - 2000
in/min	4.00 - 78700	4.00 - 60000	4.00 - 24000
m/sec	0.10 - 33.30	0.10 - 25.40	0.10 - 10.16
ft/sec	0.10 - 109	0.10 - 83.33	0.10 - 33.30
Length	0 - 99999 m / 0 - 99999 ft / 0 - 99999 in		
Accuracy	±0.02% of reading ±1 digit		
Sensing Distance	600 mm / 24 in max. (optical)		
Operating Temp.	0 to 50°C (32 to 122°F)		
Housing Material	ABS		
Dimensions	175 x 60 x 28 mm (7 x 2.5 x 1 in)		

- Measures rotational & surface speed
- Non-contact measurement in RPM
- Contact measurement in RPM, m/min, ft/min, yd/min (user selectable)
- 5 digit display
- Auto power off function

Includes cone & funnel contact tips, reflective tape, 9V battery, user manual

SPECIFICATIONS

Measuring Ranges:	
Rotation	10.0 - 99999 RPM (Non-contact) 10.0 - 19999 RPM (Contact)
Surface Speed (Contact)	1.0000 - 9999.9 m/min 3.0000 - 30,000 ft/min 1.0 - 10,000 yd/min
Resolution:	
RPM	0.001/0.01/0.1/1
M/Min	0.0001/0.001/0.01/0.1
Ft/Min	0.0001/0.001/0.01/0.1
Yd/Min	0.0001/0.001/0.01/0.1
Accuracy	±(0.1% of rdg. +2 digit)
Measure Distance	5-30 cm / 2-13 inches (non-contact)
Sampling Time	1 second (>60RPM), >1 second (10~60RPM)
Operating Temp.	0 to 50°C (32 to 122°F), < 80% RH
Dimensions	267 x 178 x 82 mm (10.5 x 7 x 3.2 in)


TACH-10

ORDERING INFORMATION

AB/TACH20	Combo Tachometer
AB/TACH-10	Contact / Non-Contact Tachometer

Exttech Tachometer

- Measures RPM & surface speed
- Pocket size
- Laser guided non-contact measurements to 4.9 ft
- Reversible 5 digit LCD display
- Min/Max/Last reading memory

Complete with cone tip and wheel for rpm or linear surface speed, four AAA batteries, and reflective tape.

SPECIFICATIONS

Range	5 to 99,999 rpm (photo mode) 0.5 to 19,999 rpm (contact mode)
Surface Speed (Contact mode)	2.0 to 78,740 inches/min 0.2 to 6560 ft/min 0.05 to 1999.9 m/min
Accuracy	±(0.1% rdg +1 digit)
Sampling Time	1 sec
Resolution	0.1rpm (<1000 rpm); 1rpm (>1000 rpm)



ORDERING INFORMATION

EX/RPM40	Pocket Laser Photo/Contact Tachometer
----------	---------------------------------------